

KONGSBERG AUTOMOTIVE ASA



PRODUCT CATALOG Ver. 1.3

GENERAL	1
SCANIA	2
VOLVO TRUCK	3
DAF	4
LEYLAND	5
RENAULT TRUCK	6
MAN	7
ERF	8
FODEN	9
SISU	10
HYUNDAI	11
PREVOST	12
ISUZU	13
BOVA	14
DAIMLER CHRYSLER	15

SCANIA



622107AM



622109AM



622190AM



622199AM



624199AM



SCANIA



624502AM



624503AM




625359AM

REPLACED BY 627692AM

627692AM




Part No.	Description	Pos. No.	Fits	Notes
622107AM	Clutch Servo		360717	
622158AM	Repair Kit	101	550453	
622135AM	Repair Kit		550422	Ø95 Servo, old version
622161AM	Repair Kit		550451	Ø95 Servo, old version




034-4706


Part No.	Description	Pos. No.	Fits	Notes
622109AM	Clutch Servo		360719	
622158AM	Repair Kit	101	550453	




Part No.	Description	Pos. No.	Fits	Notes
622190AM	Clutch Servo		374116	
625282AM	Repair Kit	101	550465	Main Kit
625283AM	Repair Kit	102	550466	Air Valve
625285AM	Repair Kit	103	550467	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
622199AM	Clutch Servo		1331770	
625282AM	Repair Kit	101	550465	Main Kit
625283AM	Repair Kit	102	550466	Air Valve
625285AM	Repair Kit	103	550467	Spool Assy



Part No.	Description	Pos. No.	Fits	Notes
624199AM	Clutch Servo		1337966	
625282AM	Repair Kit		550465	Main Kit
625283AM	Repair Kit		550466	Air Valve
625285AM	Repair Kit		550467	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
624502AM	Master Cylinder		1358801	Ø26
623157AM	Repair Kit	101	550464	




034-8887

Part No.	Description	Pos. No.	Fits	Notes
624503AM	Master Cylinder		1361136	Ø26
623157AM	Repair Kit	101	550464	
623122AM	Repair Kit	14	391543	Short
624504AM	Repair Kit	14	1361186	Long



Part No.	Description	Pos. No.	Fits	Notes
625359AM	Servomaster		1421186	
628131AM	Repair Kit	101	1484715	Main Kit



Part No.	Description	Pos. No.	Fits	Notes
627692AM	Servomaster MK 2.1			

VOLVO



626392AM



626639AM



628492AM




628493AM




628494AM




Part No.	Description	Pos. No.	Fits	Notes
626392AM	Clutch Servo		1673067	Ø80 mm, Air conn. M16 filter
626392AM	Clutch Servo		1655639	
626703AM	Repair Kit	101	85102140	Main rep. kit
627621AM	Repair Kit	102		




Part No.	Description	Pos. No.	Fits	Notes
626639AM	Clutch Servo		1521371	Ø95 mm, Air conn. M16 filter
626669AM	Clutch Servo		1668501	Ø95 mm, Air conn. M16 filter
627366AM	Repair Kit	101	3093099	1668501 and 1521371
627618AM	Repair Kit	102		Air Valve
622095AM	Repair Kit		270586	Fits 1655435 (Old version)




Part No.	Description	Pos. No.	Fits	Notes
626639AM	Clutch Servo		1671953	Ø95 mm, Air conn. M16 filter
627182AM	Repair Kit	101	3093100	1671953 and 1069205
627619AM	Repair Kit	102		Air Valve, depressurized




Part No.	Description	Pos. No.	Fits	Notes
628492AM	Clutch Servo		8171720	Ø100 mm, VT-gearboxes
628476AM	Repair Kit	101	85102142	Main Kit
627619AM	Repair Kit	102		Air Valve, depressurized
628477AM	Repair Kit	103	85102141	Cover w/bellow



Part No.	Description	Pos. No.	Fits	Notes
628493AM	Clutch Servo		8171721	Ø100mm, GR-gearboxes (bracket installation)
628476AM	Repair Kit	101	85102142	Main Kit
627619AM	Repair Kir	102		Air Valve, depressurized
628477AM	Repair Kit	103	85102141	Cover w/bellow



Part No.	Description	Pos. No.	Fits	Notes
628494AM	Clutch Servo		8171700	Bus installation
628476AM	Repair Kit	101	85102142	Main Kit
627619AM	Repair kit	102		Air Valve, depressurized
628477AM	Repair Kit	103	85102141	Cover w/bellow



DAF



626760AM



626761AM



626762AM



628036AM



628258AM



DAF



628259AM



628260AM



628275AM



628276AM



628277AM



DAF



628447AM



628448AM




628449AM




628450AM




Part No.	Description	Pos. No.	Fits	Notes
626760AM	Master Cylinder		1348733	Ø26
627200AM	Repair Kit	101	1373531	
625445AM	Push Rod	14	1357761	



Part No.	Description	Pos. No.	Fits	Notes
626761AM	Master Cylinder		1348734	Ø24
627202AM	Repair Kit	101	1373533	
625445AM	Push Rod	14	1357761	




Part No.	Description	Pos. No.	Fits	Notes
626762AM	Master Cylinder		1348735	Ø22
627201AM	Repair Kit	101	1373532	
625445AM	Push Rod	14	1357761	




034-8467

Part No.	Description	Pos. No.	Fits	Notes
628036AM	Clutch Servo		1438606	BOVA Bus, with wear indicator
626787AM	Repair Kit	101	1348878	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy
624988AM	Repair Kit	104		Wear indicator




Part No.	Description	Pos. No.	Fits	Notes
628258AM	Clutch Servo		1443523	Push Rod 16 mm soft, xlong
628305AM	Repair Kit	101	1443527	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy




8197-16204


Part No.	Description	Pos. No.	Fits	Notes
628259AM	Clutch Servo		1443522	Push Rod 16 mm soft,short
628305AM	Repair Kit	101	1443527	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
628260AM	Clutch Servo		1443524	Push Rod 16 mm soft, short wear indicator
628305AM	Repair Kit	101	1443527	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy
624988AM	Repair Kit	104		Wear indicator




Part No.	Description	Pos. No.	Fits	Notes
628275AM	Clutch Servo		1443530	Supersedes 625111AM 626580AM and 626784AM
626787AM	Repair Kit	101	1348878	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
628276AM	Clutch Servo		1443520	Supersedes 622501AM 626642AM and 626785AM
628304AM	Repair Kit	101	1443525	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
628277AM	Clutch Servo		1443521	Supersedes 622500AM 626708AM and 626786AM
628304AM	Repair Kit	101	1443525	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
628447AM	Clutch Servo		1443533	Push Rod 12mm, xlong
626787AM	Repair Kit	101	1348878	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
628448AM	Clutch Servo		1450047	Push Rod 16 mm short hardened
628305AM	Repair Kit	101	1443527	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy



Part No.	Description	Pos. No.	Fits	Notes
628449AM	Clutch Servo		1443529	Push Rod 16mm hardned, xlong
628305AM	Repair Kit	101	1443527	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy



Part No.	Description	Pos. No.	Fits	Notes
628450AM	Clutch Servo		1443531	Supersedes 626400AM and 626783AM
626787AM	Repair Kit	101	1348878	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy



LEYLAND



622504AM



625290AM



625826AM



626564AM



626565AM



LEYLAND



627497AM




627498AM




627499AM




Part No.	Description	Pos. No.	Fits	Notes
622504AM	Clutch Servo		ACU 8944	
625218AM	Repair Kit	101	1291857	



Part No.	Description	Pos. No.	Fits	Notes
625290AM	Clutch Servo		AXU 0132	
625475AM	Repair Kit	101	FBU 9623	




Part No.	Description	Pos. No.	Fits	Notes
625826AM	Master Cylinder		ACHD 274	Ø26, Straight outlet, ½"-20UNF
626608AM	Repair Kit	101	AMPA 852	
624262AM	Push Rod	14		




034-5959


Part No.	Description	Pos. No.	Fits	Notes
626564AM	Master Cylinder		ACHD 722	Ø26, Angled outlet
626608AM	Repair Kit	101	AMPA 852	
624262AM	Push Rod	14		




Part No.	Description	Pos. No.	Fits	Notes
626565AM	Master Cylinder		ACHG 221	Ø26, Straight outlet, M14x1,5
626608AM	Repair Kit	101	AMPA 852	
624262AM	Push Rod	14		




Part No.	Description	Pos. No.	Fits	Notes
627497AM	Clutch Servo		ATRA 458	Supersedes ACHG 028/ACHG 664
627629AM	Clevis	ATRA 329		Supersedes ACHG 665
627622AM	Repair Kit	101	AMPB 893	
627623AM	Repair Kit	102	AMPB 892	
627034AM	Repair Kit	103	ATRA 398	



Part No.	Description	Pos. No.	Fits	Notes
627498AM	Clutch Servo		ATRA 460	Supersedes ACHC 035/ACHG 662
627828AM	Clevis	ATRA 378		Supersedes ACHG 663
627622AM	Repair Kit	101	AMPB 893	
627623AM	Repair Kit	102	AMPB 892	
627034AM	Repair Kit	103	ATRA 398	



Part No.	Description	Pos. No.	Fits	Notes
627499AM	Clutch Servo		ATRA 462	Supersedes ACHC 450
627622AM	Repair Kit	101		Main Kit
627623AM	Repair Kit	102		Air Valve
627624AM	Repair Kit	103	ATRA 398	Spool Assy



RENAULT VI



623104AM



623105AM



623106AM



624248AM



625384AM



625524AM



626159AM



626162AM




626853AM



627612AM




Part No.	Description	Pos. No.	Fits	Notes
623104AM	Master Cylinder		5000877187	Ø26




034-4629

Part No.	Description	Pos. No.	Fits	Notes
623105AM	Master Cylinder		5000877188	Ø28




034-4628

Part No.	Description	Pos. No.	Fits	Notes
623106AM	Master Cylinder		5000792359	Ø26
626243AM	Repair Kit	101		
624262AM	Push Rod	14	5001834843	




034-4627

Part No.	Description	Pos. No.	Fits	Notes
624248AM	Master Cylinder		5010251357	Ø28
626165AM	Repair Kit	101		
624262AM	Push Rod	14	5001834843	




034-8901


Part No.	Description	Pos. No.	Fits	Notes
625384AM	Clutch Servo		5010244208	Ø80 mm
626731AM	Repair Kit	101	5001843793	Main Kit
626734AM	Repair Kit	102		Air Valve
625322AM	Repair Kit	103	5001830262	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
625524AM	Clutch Servo		5010244224	Ø100 mm depressurized
626733AM	Repair Kit	101	5001843797	Main Kit
626734AM	Repair Kit	102	5001843798	Air Valve
626735AM	Repair Kit	103	5001843799	Spool Assy




Part No.	Description	Pos. No.	Fits	Notes
626159AM	Master Cylinder		5001834842	Ø28
626163AM	Repair Kit	101	5001834844	
626166AM	Repair Kit	102	5001834795	
624262AM	Push Rod	14	5001834843	




Part No.	Description	Pos. No.	Fits	Notes
626162AM	Clutch Servo		5010244402	Supersedes 622206AM and 625385AM
626729AM	Repair Kit	101	5001843783	Main Kit
626732AM	Repair Kit	102	5001843782	Air Valve
625322AM	Repair Kit	103	5001830262	Spool Assy



Part No.	Description	Pos. No.	Fits	Notes
626853AM	Clutch Servo		5010245752	Ø80 mm
626731AM	Repair Kit	101	5001843793	Main Kit
627392AM	Repair Kit	102		Air Valve
625322AM	Repair Kit	103	5001830262	Spool Assy



Part No.	Description	Pos. No.	Fits	Notes
627612AM	Clutch Servo		5010244209	With Split Protection Valve
626734AM	Repair Kit	102	5001843798	Air Valve



034-88905

MAN



623109AM



623160AM



625586AM




627052AM



628027AM




Part No.	Description	Pos. No.	Fits	Notes
623109AM	Master Cylinder		81.30715-6120	Ø26
625977AM	Repair Kit	101	81.30715-6139	




034-2843

Part No.	Description	Pos. No.	Fits	Notes
623160AM	Master Cylinder		81.30715-6119	Ø24
625976AM	Repair Kit	101	81.30715-6138	




034-2812


Part No.	Description	Pos. No.	Fits	Notes
625586AM	Clutch Servo		81.30725-6051	Without wear indicator
622427AM	Repair Kit	101	81.30725-6061	Main Kit



Part No.	Description	Pos. No.	Fits	Notes
627052AM	Clutch Servo		81.30725-6092	Mineral Oil
629327AM	Repair Kit	101	81.30725-6102	Main Kit
629566AM	Repair Kit	102	81.30725-6103	Pos.sensor



Part No.	Description	Pos. No.	Fits	Notes
628027AM	Clutch Servo		81.30725-6093	Supersedes 625436AM
628368AM	Repair Kit	101	81.30725-6097	
628369AM	Repair Kit	102	81.30725-6098	
627117AM	Repair Kit		81.30725-6090	For 625436AM before 01.01.2000



ERF



625536AM

No product
image


626693AM



Part No.	Description	Pos. No.	Fits	Notes
625536AM	Master Cylinder		300255-1	Ø28
626165AM	Repair Kit	101	149520-8	
626166AM	Repair Kit	102	149521-4	
625537AM	Push Rod	14	300256-8	

Exploded View is under construction

Part No.	Description	Pos. No.	Fits	Notes
626693AM	Clutch Servo		403778-3	
622522AM	Repair Kit	101	300194-2	



FODEN



625671AM



625672AM

No product
image


626246AM

No product
image


626397AM




Part No.	Description	Pos. No.	Fits	Notes
625671AM	Clutch Servo		42-00215-000	Ø100 mm
626787AM	Repair Kit	101		Main Kit
626789AM	Repair Kit	102		Air Valve
626790AM	Repair Kit	103		Spool Assy



Part No.	Description	Pos. No.	Fits	Notes
625672AM	Master Cylinder			




Part No.	Description	Pos. No.	Fits	Notes
626246AM	Master Cylinder			



8187-17024

Part No.	Description	Pos. No.	Fits	Notes
626397AM	Clutch Servo		42-00249-000	Ø80 mm
627030AM	Repair Kit	101		Main Kit
627033AM	Repair Kit	102		Air Valve
627034AM	Repair Kit	103		Spool Assy




SISU



622502AM



Part No.	Description	Pos. No.	Fits	Notes
622502AM	Clutch Servo		175-201-1622	Ø80 mm
622522AM	Repair Kit	101		Main Kit




HYUNDAI



627026AM



Part No.	Description	Pos. No.	Fits	Notes
627026AM	Clutch Servo		41700,6A700	Ø80 mm
627162AM	Repair Kit	101		Main kit
627163AM	Repair Kit	102		Air Valve
627164AM	Repair Kit	103		Spool Assy




PREVOST



624410AM



Part No.	Description	Pos. No.	Fits	Notes
624410AM	Clutch Servo		520138	Ø80 mm
622522AM	Repair Kit	101		Main Kit
626205AM	Repair Kit	102		Air Valve




ISUZU



625559AM



Part No.	Description	Pos. No.	Fits	Notes
625559AM	Clutch Servo		1-31800-404-0	Ø100 mm
625960AM	Repair Kit	101		Main Kit
626622AM	Repair Kit	102		Air Valve
626626AM	Repair Kit	103		Spool Assy




BOVA



628036AM



Part No.	Description	Pos. No.	Fits	Notes
628036AM	Clutch Servo		1438606	BOVA Bus, with wear indicator
626787AM	Repair Kit	101	1348878	Main Kit
628306AM	Repair Kit	102	1443526	Air Valve, depressurized
626790AM	Repair Kit	103	1348880	Spool Assy
624988AM	Repair Kit	104		Wear indicator



DAIMLER CHRYSLER



625375AM

